

LIST OF UP TO DATA ISSUED BULLETINS FOR SZD-59 ACRO GLIDERS

Item	Bulletin no	Factory No.	C O N C E R N S	Way of introducing	NOTES
1.	BK-001/SZD-59/95	X-150 to B-2163	Introduced issue II of FM, and revisions to TSM	After this Bulletin is obtained.	
2.	BK-002/SZD-59/96	X-150 to B-2168	Introduced issue III of FM and pages of TSM	On receiving this Bulletin	
3.	BK-003/SZD-59/96	X-150 to B-2171	Introduced issue II of TSM	Mandatory on receiving this Bulletin	
4.	BK-004/SZD-59/97	B-2157 to B-2164 B-2166 to B-2175	Rudder modification	Mandatory on receiving this Bulletin	
5.	BK-005/SZD-59/98	X-150 ,B-2157 to B-2178	TSM-replacement of page.	On receiving this Bulletin.	
6.	BE-006/SZD-59/98	All gliders	Extension of service life up to 4000 flying hours.	Mandatory on completing 1500 hours total flying time on glider	
7.	BE-007/SZD-59/98	All gliders	Replacement of “ Roger hook” on cockpit rear rim.	.To operator discretion.	
8.	BE-008/SZD-59/99	X-150, B-2157 to B-2172	Elevator actuating lever in the fuselage aft portion.	On receiving this Bulletin.	Polish AD Nr SP-0032-1999-A

9.	BE-009/SZD-59/2009	All gliders	Aerobatic manoeuvres scope extending with „tail slide”.	On receiving this Bulletin.	
10.	BE-010/SZD-59/2009	All gliders	Inspection of the fuselage frame joints.	On receiving this Bulletin.	EASA AD nr 2009-0140-E
11.	BE-011/SZD-59/2009	All gliders	Replacing front tube of the fuselage frame.	Depending on results of the inspection described by BE-010/SZD-59/2009 : at once or during next 500 hours overhaul	EASA AD no 2009-0210