

MANUALS

Author	Document	Vrs.	Date of Issue	Current Revision
PD-PS „PZL Bielsko”	Instrukcja Użytkowania w Locie	PL	Issue III, Nov. 10 1995	Rev. 1, Apr. 15, 2009
	Flight Manual	EN	Issue III, Nov. 10 1995	Rev. 1, Apr. 15, 2009
	Flughandbuch	DE	Issue III, Nov. 10 1995	Rev. 1, Apr. 15, 2009
	Technical Service Manual with the Schedule of Maintenance Works	PL	Issue II, July 1996	Rev. 2, Dec. 02, 1998
	Technical Service Manual with the Schedule of Maintenance Works	EN	Issue II, July 1996	Rev. 2, Dec. 02, 1998
	Wartungshandbuch	DE	Issue II, July 1996	Rev. 2, Dec. 02, 1998
	Instrukcja Napraw	PL	Issue I, Sep. 1996	No revisions
	Repair Manual	EN	Issue I, Sep. 1996	No revisions
	Reparaturhandbuch	DE	Issue I, Sep. 1996	No revisions
	Spare Parts Catalogue	PL, EN, DE	Issue I, 1998	No revisions

SERVICE BULLETINS

SB No.	Vrs.	S/N	Subject	Compliance	Notes
BK-01-59-95	PL, EN	S/N: from X-150 to B-2163	Changes into TSM	After receiving of SB	
BK-02-59-96	PL, EN	S/N: from X-150 to B-2168	New edition (III) of FM, changes into TSM	After receiving of SB	
BK-03-59-96	PL, EN	S/N: from X-150 to B-2171	New edition (II) of TSM	After receiving of SB	
BK-04-59-97	PL, EN	S/N: from B-2157 to B-2164; from B-2166 to B-2175	Rudder modification	After receiving of SB	
BK-05-59-98	PL, EN	S/N: X-150, od B-2157 do B-2178	Changes into TSM	After receiving of SB	
BE-06-59-98	PL, EN	All S/N	Extending of life limit up to 4 000 FH	Mandatory after 1500 FH	
BE-07-59-98	PL, EN	S/N: X-150 & from B-2157 to B- 2172	Replacement of Roger Hook	Acc. to User's decision	
BE-08-59-99	PL, EN	S/N: X-150 & from B-2157 to B- 2172	Elevator acutating lever	After receiving of SB	SP-0032- 1999-A
BE-09-59-09	PL, EN	All S/N	Aerobatic – tail slide	After receiving of SB	

BE-10-59-09	PL, EN	All S/N	Inspection of fuselage frame joints	After receiving of SB	EASA AD 2009-0140-E
BE-11-59-09	PL, EN	All S/N	Replacing of fuselage frame part	In case of crack found or during the nearest 500 FH maintenance	EASA AD 2009-0210

PL – Polish, EN – English

END OF RECORD