

MANUALS

Issued by	Document	Vrs.	Date of Issue	Current Revision
PD-PS „PZL Bielsko”	Instrukcja Użytkowania w Locie	PL	Issue IV, Nov. 1991	Rev. 3, May 18, 2012
	Flight Manual	EN	Issue IV, Aug. 1991	Rev. 3, May 18, 2012
	Flight Manual	CAD	Issue IV, Mar. 1993	Rev. 2, May 25, 1995
	Flughandbuch	DE	Issue IV, Nov. 1991	Rev. 3, Dec. 19, 1996
	Opis Techniczny Instrukcja Obsługi Technicznej Terminarz Prac Okresowych Szybowca	PL	Issue IV, Aug. 1991	Rev. 4, May 15, 2012
	Technical Service Manual Technical Description Periodic Works	EN	Issue IV, Aug. 1991	Rev. 4, May 18, 2012
	Technical Service Manual Technical Description Periodic Works	CAD	Issue IV, Mar. 1993	Rev. 4, May 18, 2012
	Wartungshandbuch	DE	Issue IV, August 1991	Rev. 3, Dec. 19, 1996
	Instrukcja Napraw	PL	Issue II, 1991	Rev. 1, Sep. 12, 2007
	Repair Manual	EN	Issue II, 1991	No revisions
	Reparaturhandbuch	DE	Issue II, 1991	No revisions
	Spare Parts Catalogue	EN	Issue I, Aug. 1991	-
	Ersatzteil - Katalog	DE	Issue I, Aug. 1991	-

SERVICE BULLETINS

SB No.	Vrs.	S/N	Subject	Compliance	Notes
BE-01-55-1-89	PL	S/N X-144 and up	Supplements to FM with additional notes on SZD-55-1 operation / sealing the wing-fuselage gap with tape, pilots back rest locking		
BE-02-55-1-89	PL	S/N X-144 and up	Introduction of revisions to FM and TSM extending or specifying the operation limitations	Replacing of pages in FM and TSM	
BE-03-55-1-90	PL EN	From S/N 551190001	Revisions to FM and TSM conc. operation of valve of tail water ballast tank	Replacing of pages in FM and TSM	

BE-04-55-1-90	PL EN	All S/N with C.G. hook	Revisions to FM, issue 3 conc. winch-launching	Replacing of pages in FM and TSM	
BE-05-55-1-90	PL EN	S/N X-144, X-146 & from S/N 551190001 up	Revision to FM to bring it to compliance with the wording of current Airworthiness Statement	Replacing of pages in FM and TSM	
BI-06-55-1-92	PL EN	From S/N 551190001	Changes to the tolerance of rudder design deflections		
BE-07-55-1-94	PL EN	From S/N X-144 to 551193065	Revisions to FM and TSM resulting of operation experience, as well as corrections to the Manuals wording	Replacing of pages in FM and TSM	
BE-08-55-1-95	PL EN	S/N X-144, X-146 & from 551190001 to 551191025	Revisions to FM and TSM concerning stall warning	Replace the pages in FM and TSM	
BE-09-55-1-95	PL EN	All S/N	Use of PR-400s airspeed indicator together with SP-3 stall warning monitor	Replacing of pages in FM and TSM	
BE/R-10-55-1-96	PL EN	All S/N	Extending of service life up to 3 000 FH		
BE/R-11-55-1-03	PL EN	S/N 551193056	Extending of service life up to 4 500 FH	After reaching 3 000 FH	
BE/R-12-55-1-09	PL EN	All S/N	Extending of service life up to 12 000 FH		

PL – Polish, EN – English

END OF RECORD