



ALSTAR PZL GLIDER
Sp. z o. o.
ul. Cieszyńska 325,
43-300 Bielsko-Biała, Poland
tel.: +48 33 812 50 26,
fax: +48 33 812 3739
office@szd.com.pl
www.szd.com.pl

SERVICE INFORMATION LETTER

DATE: March 21, 2013 **SIL-001/SZD/2013**

SUBJECT: Fuselage front fitting – requirements of BE-049/SZD-503/2000.

MODELS AFFECTED: SZD-50-3 „Puchacz” (OSTIV’76 vrs. & acc. to JAR-22)

TIME OF COMPLIANCE: Up to Owner discretion, but only if replaced fuselage front fitting acc. to BE-049/SZD-503/2000.

NOTE

Incomplete review of all the information in this document can cause errors. Please read the entire Service Information Letter to make sure you have a complete understanding of the requirements.

BASEGROUND OF THE SIL:

This SIL includes the information for Users of SZD gliders, for which Allstar PZL Glider Sp. z o.o. is a Type Certificate Owner.

No further checks as specified in BE-048/SZD-503/2000 of the fuselage front fitting are necessary.

Concurrently, the requirements of section 3.3, subsection 2.3.4 „Technical Service Manual with the Schedule of Maintenance Works”, issue III dated August 1980 & section 15.4.7, subsection 7 „Technical Service Manual”, issue I (JAR 22) dated May 1994, are in force.

- END -

Issued			Revised			Page No.	Rev.
DAY	MO	YEAR	DAY	MO	YEAR	1 of 1	A
21	03	2013	21	03	2013		