

LIST OF UP TO DATA ISSUED BULLETINS FOR SZD-55-1” GLIDERS

Item	Bulletin no	Factory Nos	C O N C E R N S	Way of introducing	NOTES
1.	BE-1/55-1/89	X-144 and next	Supplements to FM with additional notes on SZD-55-1 operation /sealing the wing-fuselage gap with tape, pilots back rest locking.		Only in Polish
2.	BE-2/55-1/89	X-144 and X-145	Introduction of revisions to FM and TSM extending, or specifying the operation limitations.		Only in Polish
3.	BE-3/55-1/90	From s/n 551190001	Revisions to FM and TSM conc. operation of valve of tail water ballast tank.	Replace the pages in FM and TSM.	
4.	BE-4/55-1/90	All gliders with C.G hook	Revisions to FM, issue 3 conc. The winch-launched take-off.	Replace the pages in FM.	
5.	BE-5/55-1/90	X-144, X-146 and from s/n 551190001.	Revision to FM to bring it to compliance with the wording of currant Airworthiness Statement.	Replace the pages in FM issue 3.	
6.	BI-6/55-1/92	From s/n 551190001	Changes to the tolerance of rudder design deflections.	Introduce the revision in FM.	
7.	BE-7/55-1/94	X-144 to 551193065	Revisions to FM and TSM resulting of operation experience, as well as corrections to the Manuals wording.	.	
8.	BE-8/55-1/95	X-144, X-146 and from 551190001 to 551191025'	Revisions to FM and TSM conc. The stall warning.		
9.	BE-9/55-1/95	All gliders	Use of PR-400s airspeed ind. together with SP-3 stall warning monitor.		
10.	BE/R-10/55-1/96	All gliders	Extension of SZD-55-1 sailplane service life up to 3000 flying hours.	Mandatory Bulletin.	
11.	BE/R-11/55-1/2003	s/n 551193056	Extension of service life on SZD-55-1 s/n 551193056 to 4500 flying hours	After reaching on a glider 3000 h total flying hours	