

SB No.	Vrs.	S/N	Subject	Compliance	Notes
BK-001/77/ Seat belts/J5.00.00	PL	All seat belts produced before 01.04.1977	Change of locking spring	Mandatory	
BI-002/80/ Seat belts/J5.00.00	PL, EN	All seat belts manufactured before 01.04.1977	Seat belts change and information about length	Mandatory for seat belts without performed BK-001/77	
BE-03/J5/81/Seat belts/J5.00.00	PL	All seat belts	Seat belts exploitation	Mandatory	
BK-004/82/ Seat belts/J5.00.00	PL	All seat belts	Changes in Seat belts manual	Mandatory for seat belts J5.70.00	
BE-005/83/ Seat belts/J5.00.00	PL, EN	All seat belts with plastic deformation of locking spring	Excessive deformation of locking spring	According to User's decision	
BR-001/ SZD-III.A-56/88	PL	Towing hooks SZD-III A-56. S/N N1-001 up to N1-225	Check for malfunctions	Mandatory	
BE-006/93/J5/ Seat belts/J5.00.00	PL, EN	All seat belts	Seat belts exploitation	According to User's decision	
BE-007/94 Control cables	PL, EN	All control cables	Control cable life time and exploitation	Mandatory	
BE-002/SZD-III. A-56/97	PL,	All SZD-III A-56 towing hooks	Towing hook exploitation	Mandatory	
BE-001/SZD/2011	PL, EN	All types of SZD gliders except SZD-54-2 "Perkoz"	Flight instruments exploitation	According to User's decision	
SIL-001/SZD/2012	PL, EN	All SZD Allstar gliders	Clarification of BE-043/92 „Jantar”	According to User's decision	NEW
SIL-002/SZD/2012	PL, EN	SZD-48-3 „Jantar Std. 3”, SZD-50-3 „Puchacz” (OSTIV'76 vrs. & acc. to JAR-22), SZD-59 „Acro”.	Terms of use and further maintenance of the aircraft instruments different than „PZL-WARSZAWA II”, which have been applied so far for SZD gliders.	In case of assembling into instrument panel (panels).	NEW

PL – Polish, EN – English

END OF RECORD